

CERTIFICATE

Welding of railway vehicles and components according to EN 15085-2

This is to certify that **DIMSA DEMİR CELİK ÜRN. MAK. SAN. BOYA NAK. INS.
TAAH. SAN. VE TIC. LTD. STİ.**
Hanlıköy Mahallesi Akgün Cad. No:27 Arifiye
54580 SAKARYA
TURKEY

is qualified to perform welding work within the range of certification of:

Certification level CL1 according to EN 15085-2

Field of application: • New construction of components for bogies and battery boxes, cable channels, components for tie rods, water containers, garbage containers, air ducts, brake clinder, gearbox, stainless handle, hvac carcass, window and seat frames

Range of certification

Welding process according to EN ISO 4063	Material group according to CEN ISO/TR 15608	Dimensions	Comments
131	23.1	t ≥ 1.5 mm	FW
	23.1	t = 1.5 - 6 mm	BW
135	1.2	t = 1 - 60 mm	-
141	8.1	t = 1.4 - 2.6 mm	BW
	22	t = 1.5 - 6 mm	FW
	8.1	t = 2.5 - 5 mm	FW

(continuation: see reverse)

Responsible welding coordinator: Onur DEDE (IWE)

born: 18.07.1986

Deputy with equal rights: -

Deputy: Hüseyin INAN (Level C)


born: 12.05.1986

Certificate no.: GSISLV-TR/15085/CL1/020/0A3/20

Valid: from 19.06.2020 to 18.06.2023

Issued on: 19.06.2020

Auditor: KARAMAN
General regulations (see reverse)



GSI SLV-TR Kaynak Teknolojisi Test ve
Mesleki Gelişim Merkezi Ltd. Şti.

Çiğdem Mahallesi Gökkuşuğu Sitesi Mavi Blok No: 37-38
06520 Balgat Çankaya / ANKARA

www.gsi.com.tr

Certificate no.: GSISLV-TR/15085/CL1/020/0A3/20

Continuation of range of certification

Welding process according to EN ISO 4063	Material group according to CEN ISO/TR 15608	Dimensions	Comments
785	8.1	D = 2.46 - 7.05 mm	-

General regulations

according to EN 15085-2

Revocation of the Certificate

The national safety authority or the manufacturer certification body issuing this certificate may revoke the certificate if:

- there are justified doubts as to the proper execution of the welding work according to the stated standards,
- there are justified doubts as to the proper welding coordination according to the stated standards,
- no recognized welding coordinator is available any longer,
- no valid qualification test certificates for the welders and welding operators according to the specified standards are available,
- welders or welding operators without tested qualifications have been entrusted with the execution of welding work under the stated standards,
- other conditions according to the stated standards are no longer satisfied,
- the manufacturer certification body was refused an opportunity to perform the annual verification,
- the welding manufacturer waives the certificate

The welding manufacturer shall acknowledge the revocation in writing to the manufacturer certification body. The manufacturer certification body shall notify the national safety authority.

If a valid certificate is to be renewed, the renewal must be applied for with the manufacturer certification body at least **two months** before the end of the period of validity of the current certificate.

Distribution list:

1. Applicant (original)
2. Files

GSI SLV-TR Kaynak Teknolojisi Test ve
Mesleki Gelişim Merkezi Ltd. Şti.

Çiğdem Mahallesi Gökkuşığı Sitesi Mavi Blok No: 37-38
06520 Balgat Çankaya / ANKARA

www.gsi.com.tr

F - 157 (1)